

MONUMENT RECORD

Corner I.D. #


U-13

STATE OF INDIANA - COUNTY OF MONROE

Section Twenty-three 23, Township 9 North, Range 1 West

Monument Description & Remarks: Found 1" crimped Iron Pipe, .5' out of
ground at NE Corner of section. Pipe is at base of 18" Sugar Maple at edge
of creek bed. Old fencing runs northerly & westerly. Witnessed 3/23/94.

Recovery Tie Drawing



State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 29th day of March, 1994 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office
United States Government Agency

Monroe County Surveyor
Title _____

Field Book:

94-01

Page:

4